

FIELD INSPECTION REPORT

Project Name:	Mountain Valley Pipeline	Inspector:	Matthew Grant			
Inspection Date:	Tuesday, July 14, 2020	Project Contact:	Brian Clauto			
Spread G: Giles	AR GI-243.01, 249.01, 256.02, 025 ATWS 1464, 1370, 1370A MP 211.5, 212.4, 214.5, 215	Weather:	Dry			
ACTIVE STAG	E OF CONSTRUCTION: (Check all tha	ıt apply)				
☐ Tree Felling	☐ Clearing/Grubbing ☐ Gr	ading \square Trenc	hing \Box	Str	inging/Welding	
☐ Lowering/Backfilling	☐ Final Grading ☐ Te	mp. Stabilization	. Stabilization 🗵	Do	rmant	
			Yes	No	N/A	
Are controls installed and implemented in accordance with the approved erosion and sediment control plan and stormwater management plans?						
Are all control measures properly maintained in effective operating condition in accordance with good engineering practices and, where applicable, manufacturer specifications?						
3. Areas of offsite sediment deposition observed?				\boxtimes		
Routine Main - N/A Ineffective Co - N/A	E: Inspected the following resources: S-Fe in place at the crossing. Itenance: (72-Hour Deadline from Notification of the controls: (24-Hour Deadline) from Notification of the Corrective Action: N/A	cation)	13			

The recommended corrective action deadline date applies to all conditions noted on this report unless otherwise noted. If listed condition(s) currently constitute non-compliance and/or corrective actions are not completed by the deadline, other enforcement actions may be issued to the entity responsible for ensuring compliance on the above project.

Inspector Signature: _____



Date: Tuesday, July 14, 2020

FIELD INSPECTION PHOTO LOG

<u>Project Name</u>: Mountain Valley Pipeline <u>Date</u>: Tuesday, July 14, 2020






Figure 3: On AR 256.02 near designated stream S-NN11



<u>Figure 4</u>: Designated stream S-NN12, ECD's are in place.

